Autonics **DIGITAL PRESSURE SENSOR** (Pneumatic type) **PSAN SERIES**



Thank you very much for selecting Autonics products. For your safety, please read the following before using.

Caution for your safety

*Please keep these instructions and review them before using this unit

*Please observe the cautions that follow;

↑ Warning Serious injury may result if instructions are not followed.

★The following is an explanation of the symbols used in the operation manual. **∆** caution:Injury or danger may occur under special conditions.

⚠ Warning

I. In case of using this unit with machinery (Ex: nuclear power control, medical equipment, ship, vehicle, train, airplane, combustion apparatus, safety device, crime/disaster prevention equipment, etc) which may cause damages to human life or property, it is required to install fail-safe device.

2. Do not use it in flammable gas because it does not have an explosion proof construction


- This unit shall not be used outdoors.

 If more shorten the life cycle of the product or cause electric shock.
- It is designed for the indoors environment.

 2. Do not apply the pressure beyond the rated pressure. 3. Do not use it beyond the rated power supply.
- It may cause damage to this unit.

 4. Do not make a short circuit for the load.
- 5. Please connect wire properly after checking the polarity of power.
- It may cause damage to this unit.

 6. Do not use corrosive gas or liquid as it is only for non-corrosive gas.
- 7. Do not give power to its case or twist its case strongly.



Front panel identification and function

□ Range of rating pressure: The unit label is changeable. Please use a desired measure unit label.

 ② 4 digit LED display(Red): Used to indicate measured pressure value, setting value and error message.

 ③ Output1 indicator(Red): Output 1 is ON, LED will be ON.

 ④ Output2 indicator(Green): Output 2 is ON, LED will be ON.

 ⑤ M key: Used to enter into Preset/Parameter setting mode and to save Setting mode.

⑥ ②, ② key:Used to set parameter and preset, peak value check mode, function setting or output operation mode.
② + ② key:Used for zero-point adjustment function by pressing ② + ② keys over 1 sec. simultaneously in RUN mode.

Functions

Pressure unit change function
PSAN-V01C(P) and PSAN-C01C(P) has 7 kinds of pressure unit, PSAN-01C(P) and
PSAN-1C(P) has 4 kinds of pressure unit. Please select the proper unit for application.
PSAN-V01C(P), PSAN-C01C(P): kPa, kgf/cm², bar, psi, mmHg, inHg, mmH₂O
PSAN-01C(P), PSAN-1C(P): kPa, kgf/cm², bar, psi
When using mmH₂O unit, multiply display value by 100.

*When using mmH2O unit, mulliply ulspra; value _,

Output mode change function

There are 5 kinds of control output mode in order to realize the various pressure detection.

- Hysteresis mode (H35.5): When needed to change hysteresis for detecting pressure.

- Window comparison output mode (P1.5): When needed to detect pressure in certain area.

- Hysteresis — Window comparison output mode (H3±9): When path hysteresis mode and window comparison output mode are required

- Automatic sensitivity setting mode (RUEa): When needed to set detection sensitivity automatically at proper position.

- Forced output control mode (F.aUE): When needed to display pressure with remaining comparison output OFF regardless of setting value

OControl output change function

Type of control output for Out1 and Out2 can be able to set Normally Open and Normally Closed.

* Note that Normally Open and Normally Closed provide opposite output.

Response time change function(Chattering prevention)

ns, 1000ms ne is aettina longer, the detection will be more stable by increasing the number of digital filter

• Analog output scale setting and Hold/Auto Shift setting function
• Analog voltage output scale setting: The scale function for analog output voltage (1-5VDC) is not fixed to the rated pressure range. It can be changed for User's application.
• Analog current output scale setting: The scale for analog output Current (DC4-20mA) is not fixed to the rated pressure range. It can be changed for User's application.
• Hold/Auto Shift input setting:

Hold/Auto Shift input setting ≶Hold function: A function to hold PV and Control output while signal is input. Auto Shift function: A function to compensate the setting value for changed value of reference pressure as threshold level if reference pressure of the device changes.

OKey lock function

ne key lock function prevents key operations so that conditions set in each mode. [preset/parameter mode]

are not inadvertently changed. There are 2 kinds of key lock functions available.

• LoE 1: All keys are locked: therefore it is not available to change parameter settings, preset value, zero adjustment, High/Low peak check, and 5HJ - data initialization. (Lock setting change is available)

• LoEE: Partially locked status; therefore it is not available to change parameter settings only (Lock setting change is available). Other settings are still available.

• oFF: All of the setting is available, all keys are unlocked.

②Zero-point adjustment function
The zero-point adjustment function forcibly sets the pressure value to "zero" when the pressure port is opened to atmospheric pressure. When the zero adjustment is applied, analog output [Voltage or Current] is changed by this function. (Press ☑ + ♠ keys over 1 sec. in RUN mode.)

OHigh Peak / Low Peak Hold function

This function is to diagnosis malfunction of the system caused by parasitic pressure or to check through memorizing the max./min. pressure occurred from the system.

Frror display function

Error display function		
Error display	Description	Troubleshooting
Errl	When external pressure is input while adjusting zero point	Try again after removing external pressure
Err2	When overload is applied on control output	Remove overload
Err3	When setting condition is not met in Auto sensitivity setting mode	Check setting conditions and set proper setting values
LLLL	When applied pressure exceeds Low-limit of display pressure range	Apply pressure within display pressure range
нннн	When applied pressure exceeds High-limit of display pressure range.	
-HH- -LL- -HL-	Auto shift correction error	Set the corrected setting value within setting pressure range.

*The above specifications are subject to change without notice.

Specifications Setting Gauge pressure PSAN-V01C(P)V- PSAN-01C(P)V- PSAN-1C(P)V- PSAN-C01C(P)V-Hold/Auto shift input PSAN-V01C(P)H- PSAN-01C(P)H- PSAN-1C(P)H-PSAN-C01C(P)H-0.0 to -101.3kPa 0.0 to 100.0kPa 0 to 1,000kPa 0.1kPa 2 times of rating pressure Air, Non-corrosive gas Applicable fluid Power supply 12-24VDC ±10% (Ripple P-P: Max. 10%) Current consumption Max. 50mA(Analog Current Output type Max 75mA) IPN or PNP open collector output Load voltage: Max. 30VDC • Load cu Residual voltage-NPN: Max. 1V, PNP Control output Hysteresis (* 2) Min. display range Repeat error electable 2.5ms, 5ms, 100ms, 500ms, 1000ms Linear: Max. ±1% F.S. • Output impedance: 1k\(\Omega\) Span: Max. 4VDC ±2% F.S. resolution) • Response Time: 50ms oltage out Dutput current: DC4-20mA ±2% F.S. • Linear: Max. ±1% F.S. Zero point: Max. DC4mA ±2% F.S. • Span: Max. DC16mA ±2% F.S. (***3**) 2000 1000 2000 | 1000 | 2000 | 1000 | 1000 2000 pressure unit 0.1 0.1 0.1 kgf/cm 0.001 0.001 bar 0.001 0.001 0.01 0.001 0.01 0.1 0.02 mmHg 0.4 0.8 inHg 0.02 0.03 mmH₂O 0.1 0.1 0 to 50℃: Max. ±0.5% F.S., -10 to 0℃: Max. ±1% F.S Display accuracy Min. 50MΩ(at 500VDC megger) 1000VAC 50/60Hz for 1 minute .5mm amplitude at frequency of 10 to 55Hz in each of X, Y, Z dire -10 to 50°C, Storage: -20 to 60°C 30 to 80%RH, Storage: 30 to 80%RH Front case:PC, Rear case:PC, Pressure port:Nickel Plated Brass Material Connector cable (ϕ 4, 5-wire, Length: 2m, AWG 24, Core diameter: 0.08 Number of cores: 40, Insulator diameter: ϕ 1) Approval C€ Unit weight Approx. 80g

R1/8: Th/8 model(Option)

In hysteresis output mode, detection difference is variable.

It is allowed to select one analog output type only.


Resolution(1000/2000) of min. Display interval is automatically selected depend on pressure units.

#1: (P) is PNP output type, □ of model name is as pressure port.


RC1/8: PT1/8' model(Standard), NPT1/8' NPT1/8' model(Option); *There may be ± 1digit hysteresis error by R1/8: PT1/8' model(Option) or error of pressure unit. or condensation

Output operation mode


 Window comparison output mode(□ n) ●Hysteresis mode(H55.ñ)




①It is available to set hysteresis mode(5£1, H951) and window comparison output mode when both hysteresis mode(5£1, H951) and window comparison output mode(£24, H15H) are necessary. 2 Detection hysteresis is fixed to min. display range.




●Forced output control mode(F.¤IJŁ) ①Used to display pressure with forcibly holding comparing output OFF regardless of setting value ②In parameter setting, if output operation mode setting 'aUt a' is changed to 'F.aUt', for output control mode is operated.
③OUT1, 2 can be ON/OFF manually by pressing ⑤, ⑥key while the forced output control mode is applied.



Input/Output circuit and diagram ○Analog output type(Voltage output PSAN-□□□□V-□. Current output PSAN-□□□□A-□




○Hold / Auto Shift input type(PSAN-□□□H-□)



Installation


Pressure ports are two types; standard and option. Be sure that when using an one touch fitting. (Standard: Rc1/8', Option: NPT1/8', R1/8') Please connect it by using spaner(12mm) at the metal part in order not to overload on the body when connecting one touch fitting.
Two different fixing brackets are provided for PSAN model. Select

proper one with considering your application environments. At first, please unscrew hexagon wrench bolt and assemble the bracket on this unit by fixing hexagon the wrenchbolt. In this case, tightening torque of hexagon wrench should be max. 30kgf·cm. It may cause mechanical





Bracket (PSO-B02) and front protection cover (PSO-P01) are optional to sell. Please see the pictures for installation.





if the key lock is set (lock1 or lock2), unlock the key lock before setting parameters.

Press (♠), (♦) key to change setting values.

Press (♠), (♦) key to save setting value in each parameter and move to next parameters.

When pressing (♠) key for 3 sec in the middle of parameter setting, current setting value will be saved in EEPROM and [-Uo] will flash twice, then returned to RUN mode.

High peak value check


Low peak value check


Low peak value check


Auto Shift Input Checking

(In case of Hold/Auto Shift input type

Zero point adjustment







►RUN mode

▼M

M

M

5t I Flashes in turn

pressure

sure detection el 2 setting $\#5 \pm 2$ | Flashes in turn $\#5 \pm 2$ | $\#5 \pm 1$ |

Auto setting
value

SEE | (|SE| | | |SE2|)/2

Press (♠) (♠) key for manual adjustment.

| |F| |

If there is no additional key operation within 60 sec while setting, it is returned to Run mode (Except for force output mode). Previous set values are remained.

When using the forced output function, Hold/Auto shi

*When changing pressure display unit, resolution an Hold/Auto Shift input function, preset values will be initialized as shown the table below. (When changing pressure displatunit, preset value will be automatically switched to changet pressure unit.)

(Preset Default > (Unit:kPa

values will be initialized. Instead, previous settings will become the preset values.

≤ [5Ł I] ≤ Max. display pressure – 1% of rate

Compound pressure 101.3 to 100

5t 1:50.0 H95 1:-50. Log:-50. HI GH:50.0

Preset Setting

* [run] will be flickering twice when returning to RUN mode. * Press 禽, 宮 key to change setting values. * Press M key to save setting value in each parameter and move to next parameters Automatic sensitivity setting mode

Min.display pressure

► RUN mode M 5t I Flashes in turn Min.display pressure < [5£ 1] ≤ Max. display M vel 1 sec...
H95 I
Flashes in turn 10.0 Min.display pressure ≤ [H95 I] < [5Ł I] M 5Ł2 ← 40.0 Min. display pressure < [5Ł2] ≤ Max. display pressure oressure M

Window comparison output mode

M


RUN mode M #Setting range
Min.display pressure
≤ [Lo-1] ≤ Max. display
pressure-(3×Min. display Lo-I Flashes in turn ▶ 10.0 M range) $Setting range [L_0-1]+(3\times Min. display range) \le [HI-1] \le Max. display pressure$ HI - I Flashes in turn

H452 Flashes in turn Min.display pressur

M Min.display pressure ≤ [Lo-2] ≤ Max. display pressure – (3×Min. display Lo-2 Flashes in turn → 30.0 М range)

1-limit value of Pressure attention level 2 setting HJ - 2 | HJ -Hysteresis-Window comparison output mode

RUN mode M



Ιм Zero point adjustment

I. Please press [3]+ (a) keys for over 1 sec. at the same time putting an applied pressure in state of the atmospheric pressure. 3. When the zero point adjustment is completed, it will display [32] and return to RUN mode automatically.

##I executing zero point_adjustment on external pressure

I would not return to not whose adoutnateay, the sure being at pressure point [E-r-] will flash Stimes. Please execute it in the atmospheric pressure after removing external pressure.

Please execute the property of the pressure after removing external pressure.

Please execute zero point adjustment regularly.

● Peak Hold / Auto Shift Check/Change ► RUN mode Press key for 3 sec H.PEŁ Tlashes in tum М L PEL Flashes in turn -2.1 M (★1) SHJ n Flashes in turn 50.0

₩ [-Un] will flash twice, then return to RUN mode

Caution for using

_aser marking system(CO2, Nd:YAG) _aser welding/soldering system

I Do not insert any sharp or pointed object into pressure port. It may cause malfunction and damage the sensor.

2. Be sure that this unit must avoid direct touch with water, oil, thinner etc.

3. It is ready to operate 3 sec. after it is turned 0N. Be sure not to use the product within 3 sec.

4. When using switching power supply, frame ground (F.G.) terminal of power supply should be grounded.

5. To avoid inductive noise, keep the wiring away from power line, high voltage line. It may cause malfunction.

6. When moving this unit from warm place to cold place, please remove the humidity on the cover then use it.

7. Do not press the setting button with sharp or pointed object.

8. Do not apply a tensile strength in excess of 30N to the cables or connector.

9. When using mmHzO unit, please multiply display value by 100.

10. Allowable installation environment

(i) If it shall be used indoor.

3. Pollution degree 3.

(ii) Installation Catagory II

Altitude Max. 2,000m
 Installation Catagory

Major products

roximity sensors beroptic sensors Door/Door side sensors plounters Timers Power controllers and meters achometer/Pulse(Rale) meters emperature/Humidity transducers tepping motors/drivers/motion controllers sear marking system (CA).

sal of a product improvement ment : product@autonics.com EP-KE-77-0014B

000000000